DAILY WORK ORDER	
•	Work Period: 8/24/87
	OSC: Jack D. Harmon
3.)Continue skimming oil off the 50K pool & discharge into the 12K pool in area #14. 4.)Sample areas #10 & #11 (1st floor) and begin sampling area #7 1st floor and 2nd floor pad	Yes No Continues  1.) (x) ( ) ( )  2.) (x) ( ) ( )  3.) ( ) ( ) (x)  4.) (x) ( ) ( )  5.) ( ) ( ) (x)
	EQUIPMENT USED FROM PREVIOUS DAY:  All Authorized  COMMENTS:  (4) Porta-Johns (1) Pneumatic Forklift
PERSONNEL AUTHORIZED: (1) Response Manager (1) Laborer (1) Lab Technician (2) (8) Clean-up Technician (1)	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (5) Clean-up Technician (2) (1) Lab Tech. I
Contractor Signature:  Date: 8/24/87	OSC Signature:  ack D. Home  Pate: 8/24/87
O(& X/O /	1 0/4/07